

ペイトキャストイングリール スプール対応機種一覧①	スプール																			
	RCSB	RCSB	RCSB	RCSB	RCSB	RCSB	RCSB	RCSB	RCSB	RCSB	RCSB	RCSB	RCSB	RCSB	RCSB	RCSB	RCSB	RCSB	RCSB	RCSB
STEEZ CT SV TW	700H/HL/XH/XHL																			
STEEZ SV TW	1012SV-XH/XHL	●	●	●	○	●	●	●												
	1016SV-H/HL/SH/SHL	●	●	●	○	●	●	●												
STEEZ A TW	1016CC/L-CC/H/HL/SH/SHL/XH/XHL	●	●	●	●	●	○	●												
SV LIGHT LTD	6.3R-TN/L-TN 8.1R-TN/L-TN																			
STEEZ LTD.SV	105XH/XHL																			
STEEZ LTD.SV TN	103H-TN/HL-TN																			
SS AIR	8.1R/L																			
SS SV	103/L/H/HL/SH/SHL 105XH/XHL																			
T3 AIR	6.8R-TW/L-TW/8.6R-TW/L-TW																			
Z BLACK LTD.	2020SH/SHL																			
ZILLION SV TW	1016SV/L/H/HL/SH/SHL/XXH/XXHL	●	●	●	●	●	●	●												
ZILLION TW	1516/L/H/HL/SH/SHL/XXH/XXHL																			
ZILLION TW HD	1520-CC/L-CC/H/HL/SH/SHL/XH/XHL																			
ZILLION TW HLC	1514SH/SHL/1516SH/SHL																			
TATULA SV TW	6.3R/L/7.3R/L/8.1R/L																			
TATULA TW	100H/HL/SH/SHL/XH/XHL																			
TATULA	103-TW/L/H/HL/SH/SHL/XH/XHL 100H-TW/HL/SH/SHL																			
TATULA HD CUSTOM	150H-TW/HL/SH/SHL 153H-TW/HL/SH/SHL																			
TATULA HLC	7.3R-TW/L-TW/8.1R-TW/L-TW																			
ALPHAS CT SV	70H/HL/SH/SHL	○																		
ALPHAS AIR	5.8R/L/7.2R/L																			
ALPHAS AIR STREAM CUST	7.2R/L																			
ALPHAS SV	105/L/SH/SHL																			
FUEGO CT	103H/HL/SH/SHL																			
MILLIONAIR CT SV	70H/HL/SH/SHL	○																		
18RYOGA	1016-CC/L-CC/H/HL 1520-CC/L-CC/H/HL		●	●	●	●	●	○※1	●											
RYOGA	1016/L/H/HL 2020/L/H/HL		●	●	●	●	●	●	●											
RYOGA SHRAPNEL	C3000H/L																			

○は標準装備※1 ●は装着可能 △は装着可能ですがギヤやBBに過度の負担がかかるので使用上おすすめできません。またBBの場合は分解が難しく、パーツを破損の恐れがありますので修理に出していただく事をおすすめします。
※1…本体の仕様を表現。デザイン・付属品までオプションパーツそのものが付属しているわけではありません。ベアリングはノーマルBB、CRBBのいずれかが付いています。
※2…対応しますがブレーキが強めに効きます。またその逆(例:STZSV105にSTZSV-TW1016のスプール)はブレーキ力が不足するため使えません。
※3…ベアリングキットが2セット取付可能です。 ※4…Wハンドル機種。各ハンドルノブに1ヶずつBBが入ります。 ※5…交換時ハンドルノブキャップを外す専用ドライバー(ご注文コード:199585)が必要です。
※6…ボールホルダーナット交換の際にフロントカバーを取り外す必要があります。 ※7…スタードラッグ交換によりドラッグをいっぱいにするための保管状態では、サイドカバースカート部とドラッグの間にすき間が生じます。
※8…付属品の調整ワッシャーを追加してください。 ※9…5.3、8.1を除きます。 ※…スタードラッグは右ハンドルにはRを、左ハンドルモデルにはLをお選びください。